Open Space Tree Removal

Sander's Tree Report Notes

- One (1) 75' Cottonwood Tree
 - Causing damage to neighbor's landscape/ hardscape
 - Neighbor's grade causing flooding in yard
 - Drops large limbs in neighbor's yard
 - Concern of additional damage to property, roof/gazebo, etc.
 - Arborist cannot do root barrier and recommends tree removal
- Recommend Removal of Tree and Grinding of Stump and Replanting

Sander's Cottonwood-Roots



Large Diameter
Roots growing
into neighbors
yard, causing
localized flooding,
removal of tree
needed

Storm Water Quality Facility (SWQF) Woodhaven 1-A (behind LaSalle Court)

Woodhaven SWQF 1A-CIP

- Removal of approximately 25 volunteer Cottonwood trees
- Removal of various Willow and downed/dead trees in bottom of pond causing storm system to back up and not drain
- Core-out and regrade facility for storm system to operate properly
- Planting of approximately 240 shrubs and trees on side slope of SWQF, in addition to sedges and grasses in bottom of wet pond

Woodhaven SWQF-1A Capital Improvement Project


Blocked inlet, storm system under water downed trees, overgrown



Tree growing into outlet,



Woodhaven SWQF-1A



Tree Removal at Snyder Park





Tree Removal

Walnut tree at Snyder needs to be removed due to very large cavity located in main trunk





Tree Removal

Two Birch Trees need to be removed and replaced.

Tree Removal/Replacement at Sherwood Center for the Arts



Tree Removal


Replace dead tree at Cultural Arts Facility with two (2) trees to match existing.

Tree Removal at Langer Park



Tree Removal

Removal of three trees at Langer Park



150 PlayCore Drive SE Fort Payne, AL 35967 www.gametime.com

Langer Park Sherwood OR

This play equipment is recommended for children ages Minimum Area Required

Scale: 1" = 5'-0" This drawing can be scaled only when in an 18" x 24" format

IMPOI should I equipme equipn critical fa consum ASTM